

Equip No:	36803	Inspect No:	220858	Site: M J HICKEY (PLANT HIRE) LTD Dyer & Butler Stanwell Road Feltham TW14 8NG			
Make/Model:	DOOSAN / B25NS	Job No:	674678				
Serial No:	FBA47-4410-01531	Contact:					
Cust Equip No:		Inspected:	04/12/2025				
Meter:	51	YOM:	2023		Printed:	05/12/2025	Page:

Items to Inspect	Result	Comments
Reason		
Reason for Thorough Examination	In Service - within an Interval of 12 Months	
Details of Machine		
Safe Working Load (SWL)	Kg	2500
Safe Working Load (SWL) mm	mm	500
Safe Working Load with Attachment (SWL) Kg	Not Applicable	
Safe Working Load with Attachment (SWL) mm	Not Applicable	
Inner Chain Dimension	Not Applicable	
Inner Chain Wear %	Wear %	0
Outer Chain Dimension	Not Applicable	
Outer Chain Wear %	Wear %	0
Forks Dimension	Not Applicable	
Forks Wear %	Wear %	1
Defects		
Description of Defect	Notes	Battery cable damaged recommendation replace Plastic missing out of steering column
Timescale for Repair	Notes	1 month
Declaration		
I hereby declare that the equipment described in this Report was thoroughly examined in accordance with Gn26 and...	Faults detected, action required as above	

Items to Inspect	Result	Comments
Declaration		
Do you Believe the Truck has a Defect that has an Existing or Imminent Risk of Serious Personal Injury and if the Report Needs Sending to the Local Authority	No	
Other		
Other Tests Performed	Not Applicable	
Date of Last Inspection:		
Date of Next Inspection:	04/12/2026	

Service carried out by: Engineer Name: Shane Whittaker
Signature:



Customer Name: Jeff
Signature:

