



H2Y3

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S  RT  FE  ROTATE  BIO OIL

Make / Model	2x135-7	Date:	22/04/2026
Fleet Number	H 283		
Hour Meter	1422 hrs		

Machine Serviced 250  500  1000  Service Computer reset  Service sticker updated

Service due 1841 hrs

Plant item	OK	Defect	Fuel / Fluids	OK	Defect
Rams / bushings	✓		Fuel Level	100%	
Cab Guards/Covers	N/A		Fuel connectors & pipes	✓	
Lifting eye / points	✓		Engine Oil Level	100%	
Cab glass	✓		Coolant Level	100%	
Chassis bolts & security	✓		Hydraulic fluid level	100%	
Seat secure & fully adjustable	✓		Washer fluid level	100%	
Tracks	✓		Ad-blue level	100%	
Blade / stabilizers if fitted	N/A		Refuelling Hose - present	✓	
Seat & Seat Belt	✓				
Steering if applicable	N/A				
Brakes as appropriate	N/A				

Electric	OK	Defect
Cable Connections	✓	
General Cleanliness	✓	
Battery Security	✓	

Other Checks	OK	Defect
Front left wheels	/	
Front right wheels		
Rear left wheels		
Rear right wheels		

Defects / Service Details / Notes ALL CHECKED OVER ALL GREASED AND CLEANED AROUND. ALL IN WORKING ORDER

Engineers name: AC Signature: [Signature]



H224

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	2x 85-6	Date:	14/04/2026
Fleet Number	H 224		
Hour Meter	5439 hrs		

Machine Serviced 250  500  1000  Service Computer reset  Service sticker updated

Service due 56/2 hrs

Plant item	OK	Defect	Fuel / Fluids	OK	Defect
Rams / bushings	✓		Fuel Level	100%	
Cab Guards/Covers	N/A		Fuel connectors & pipes	✓	
Lifting eye / points	✓		Engine Oil Level	100%	
Cab glass	✓		Coolant Level	100%	
Chassis bolts & security	✓		Hydraulic fluid level	100%	
Seat secure & fully adjustable	✓		Washer fluid level	100%	
Tracks	✓		Ad-blue level	N/A	
Blade / stabilizers if fitted	✓		Refuelling Hose - present	✓	
Seat & Seat Belt	✓				
Steering if applicable	N/A				
Brakes as appropriate	N/A				
Bodywork	✓				
Operating Controls	✓				
Warning Lights	✓				
Gauges/Instruments	✓				
Railings / boxing ring	N/A				
Fan & other belts / chains	✓				
Fuel cap secured	✓				
Lenses & mirrors	✓				
Rear & 360° cameras	✓				
Horn	✓				
Travel alarm	✓				
Lights / Beacons	✓				
Obvious Leaks	N/A	✗			
Safety pins & bolts	✓				
Floor mats/ Air freshener	✓				

Electric	OK	Defect
Cable Connections	✓	
General Cleanliness	✓	
Battery Security	✓	

Other Checks	OK	Defect
Front left wheels		
Front right wheels		
Rear left wheels		
Rear right wheels		

Defects / Service Details / Notes ALL CHECKED OVER, ALL GREASED AND CLEANED OVER, ALL IN WORKING ORDER

Engineers name: *AE* Signature: *[Signature]*



H254

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	2X 26-6	Date:	22/04/2026
Fleet Number	H 254		
Hour Meter	1443 hrs		

Machine Serviced 250  500  1000  Service Computer reset  Service sticker updated

Service due 1943 hrs

Plant item	OK	Defect
Rams / bushings	✓	
Cab Guards/Covers	N/A	
Lifting eye / points	N/A	
Cab glass	✓	
Chassis bolts & security	✓	
Seat secure & fully adjustable	✓	
Tracks	✓	
Blade / stabilizers if fitted	✓	
Seat & Seat Belt	✓	
Steering if applicable	N/A	
Brakes as appropriate	N/A	
Bodywork	✓	
Operating Controls	✓	
Warning Lights	✓	
Gauges/Instruments	✓	
Railings / boxing ring	N/A	
Fan & other belts / chains	✓	
Fuel cap secured	✓	
Lenses & mirrors	✓	
Rear & 360° cameras	N/A	
Horn	✓	
Travel alarm	✓	
Lights / Beacons	✓	
Obvious Leaks	N/A	
Safety pins & bolts	✓	
Floor mats/ Air freshener	✓	

Fuel / Fluids	OK	Defect
Fuel Level	100%	
Fuel connectors & pipes	✓	
Engine Oil Level	100%	
Coolant Level	100%	
Hydraulic fluid level	100%	
Washer fluid level	100%	
Ad-blue level	N/A	
Refuelling Hose - present	N/A	

Electric	OK	Defect
Cable Connections	✓	
General Cleanliness	✓	
Battery Security	✓	

Other Checks	OK	Defect
Front left wheels		
Front right wheels		
Rear left wheels		
Rear right wheels		

Defects / Service Details / Notes ALL CHECKED OVER. ALL GREASED AND CLEANED OVER. ALL IN WORKING ORDER.

Engineers name: AC Signature: [Signature]



PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	21225-62	Date:	22.04.2026
Fleet Number	219		
Hour Meter	5843 hrs		

Machine Serviced 250  500  1000  Service Computer reset  Service sticker updated

Service due 6343 hrs

Plant item	OK	Defect	Fuel / Fluids	OK	Defect
Rams / bushings	/		Fuel Level	100%	
Cab Guards/Covers	/		Fuel connectors & pipes	100%	
Lifting eye / points	/		Engine Oil Level	100%	
Cab glass	/		Coolant Level	100%	
Chassis bolts & security	/		Hydraulic fluid level	100%	
Seat secure & fully adjustable	/		Washer fluid level	100%	
Tracks	/		Ad-blue level	100%	
Blade / stabilizers if fitted	hit		Refuelling Hose - present	100%	
Seat & Seat Belt	/				
Steering if applicable	hit				
Brakes as appropriate	hit				
Bodywork	/				
Operating Controls	/				
Warning Lights	/				
Gauges/Instruments	/				
Railings / boxing ring	/				
Fan & other belts / chains	/				
Fuel cap secured	/				
Lenses & mirrors	/				
Rear & 360° cameras	/				
Horn	/				
Travel alarm	/				
Lights / Beacons	/				
Obvious Leaks	/				
Safety pins & bolts	/				
Floor mats/ Air freshener	/				

Electric	OK	Defect
Cable Connections	/	
General Cleanliness	/	
Battery Security	/	

Other Checks	OK	Defect
Front left wheels		
Front right wheels		
Rear left wheels		
Rear right wheels		

Defects / Service Details / Notes  
 All checks done, cleaned all roads

Engineers name: Ae Signature: [Signature]



PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	THWAITES - 3T	Date:	23/04/2026
Fleet Number	D 103		
Hour Meter	1999 hrs		

Machine Serviced	250 <input type="checkbox"/>	500 <input type="checkbox"/>	1000 <input type="checkbox"/>	Service Computer reset <input type="checkbox"/>	Service sticker updated <input type="checkbox"/>
------------------	------------------------------	------------------------------	-------------------------------	---	--

Service due	2053 hrs
-------------	----------

Plant item	OK	Defect	Fuel / Fluids	OK	Defect
Rams / bushings	✓		Fuel Level	100%	
Cab Guards/Covers	N/A		Fuel connectors & pipes	✓	
Lifting eye / points	N/A		Engine Oil Level	100%	
Cab glass	N/A		Coolant Level	100%	
Chassis bolts & security	✓		Hydraulic fluid level	100%	
Seat secure & fully adjustable	✓		Washer fluid level	N/A	
Tracks	N/A		Ad-blue level	N/A	
Blade / stabilizers if fitted	N/A		Refuelling Hose - present	N/A	
Seat & Seat Belt	✓				
Steering if applicable	✓				
Brakes as appropriate	✓				
Bodywork	✓				
Operating Controls	✓				
Warning Lights	✓				
Gauges/Instruments	✓				
Railings / boxing ring	N/A				
Fan & other belts / chains	✓				
Fuel cap secured	✓				
Lenses & mirrors	N/A				
Rear & 360° cameras	N/A				
Horn	✓				
Travel alarm		X → NOT FITTED.			
Lights / Beacons	✓				
Obvious Leaks	N/A				
Safety pins & bolts	✓				
Floor mats/ Air freshener	N/A				

Electric	OK	Defect
Cable Connections	✓	
General Cleanliness	✓	
Battery Security	✓	

Other Checks	OK	Defect
Front left wheels	✓	
Front right wheels	✓	
Rear left wheels	✓	
Rear right wheels	✓	

Defects / Service Details / Notes  
 ALL CHECKED OVER - ALL GREASED AND CLEANED THROUGH.  
 ALL IN WORKING ORDER.

Engineers name:	AC	Signature:	[Signature]
-----------------	----	------------	-------------



D122

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE



BIO OIL

Make / Model	THWATER 17	Date:	23/4/26
Fleet Number	D122		
Hour Meter	53 hrs		

Machine Serviced 250  500  1000  Service Computer reset  Service sticker updated

Service due	hrs		Fuel / Fluids	OK	Defect
Plant item	OK	Defect			
Rams / bushings	/		Fuel Level	% 100	
Cab Guards/Covers	/		Fuel connectors & pipes	/	
Lifting eye / points	/		Engine Oil Level	/	
Cab glass	/		Coolant Level	/	
Chassis bolts & security	/		Hydraulic fluid level	/	
Seat secure & fully adjustable	/		Washer fluid level	/	
Tracks	/		Ad-blue level	X	
Blade / stabilizers if fitted	/		Refuelling Hose - present	/	
Seat & Seat Belt	/				
Steering if applicable	/		Electric	/	
Brakes as appropriate	/		Cable Connections	/	
Bodywork	/		General Cleanliness	/	
Operating Controls	/		Battery Security	/	
Warning Lights	/				
Gauges/Instruments	/		Other Checks		
Railings / boxing ring	/		Front left wheels	/	100
Fan & other belts / chains	/		Front right wheels	/	100
Fuel cap secured	/		Rear left wheels	/	100
Lenses & mirrors	/		Rear right wheels	/	100
Rear & 360° cameras	/				
Horn	/				
Travel alarm	/				
Lights / Beacons	/				
Obvious Leaks	/				
Safety pins & bolts	/				
Floor mats/ Air freshener	/				

Defects / Service Details / Notes

Engineers name:  Signature: 



D112

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S  RT  FE  ROTATE  BIO OIL

Make / Model	THWAITES-3T	Date:	23/04/2026
Fleet Number	D112		
Hour Meter	933 hrs		

Machine Serviced 250  500  1000  Service Computer reset  Service sticker updated

Service due 1048 hrs

Plant item	OK	Defect	Fuel / Fluids	OK	Defect			
Rams / bushings	<del>100%</del> ✓		Fuel Level	100%				
Cab Guards/Covers	N/A		Fuel connectors & pipes	✓				
Lifting eye / points	N/A		Engine Oil Level	100%				
Cab glass	N/A		Coolant Level	100%				
Chassis bolts & security	✓		Hydraulic fluid level	100%				
Seat secure & fully adjustable	✓		Washer fluid level	N/A				
Tracks	N/A		Ad-blue level	N/A				
Blade / stabilizers if fitted	N/A		Refuelling Hose - present	N/A				
Seat & Seat Belt	✓		<b>Electric</b>					
Steering if applicable	✓		Cable Connections	✓				
Brakes as appropriate	✓		General Cleanliness	✓				
Bodywork	✓		Battery Security	✓				
Operating Controls	✓		<b>Other Checks</b>					
Warning Lights	✓		Front left wheels	✓				
Gauges/Instruments	✓		Front right wheels	✓				
Railings / boxing ring	N/A		Rear left wheels	✓				
Fan & other belts / chains	✓		Rear right wheels	✓				
Fuel cap secured	✓		Defects / Service Details / Notes					
Lenses & mirrors	N/A		<p>ALL CHECKED OVER. ALL GREASED AND CLEANED AROUND. * HORN NOT WORKING *</p>					
Rear & 360° cameras	N/A							
Horn		X						
Travel alarm	✓							
Lights / Beacons	✓							
Obvious Leaks	N/A							
Safety pins & bolts	✓							
Floor mats/ Air freshener	N/A							
Engineers name:						Signature:		

Defects / Service Details / Notes

Engineers name: *AC* Signature: *[Signature]*



H217

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	2x 225-6	Date:	24/04/2026
Fleet Number	H217		
Hour Meter	8193 hrs		
Machine Serviced	250 <input type="checkbox"/> 500 <input type="checkbox"/> 1000 <input checked="" type="checkbox"/>	Service Computer reset	<input checked="" type="checkbox"/>
		Service sticker updated	<input checked="" type="checkbox"/>
Service due	8693 hrs		

Plant item	OK	Defect
Rams / bushings	✓	
Cab Guards/Covers	✓	
Lifting eye / points	✓	
Cab glass	✓	
Chassis bolts & security	✓	
Seat secure & fully adjustable	✓	
Tracks	✓	
Blade / stabilizers if fitted	N/A	
Seat & Seat Belt	✓	
Steering if applicable	N/A	
Brakes as appropriate	N/A	
Bodywork	✓	
Operating Controls	✓	
Warning Lights	✓	
Gauges/Instruments	✓	
Railings / boxing ring	✓	
Fan & other belts / chains	✓	
Fuel cap secured	✓	
Lenses & mirrors	✓	
Rear & 360° cameras	✓	
Horn	✓	
Travel alarm	✓	
Lights / Beacons	✓	
Obvious Leaks	N/A	
Safety pins & bolts	✓	
Floor mats/ Air freshener	✓	

Fuel / Fluids	OK	Defect
Fuel Level	100%	
Fuel connectors & pipes	✓	
Engine Oil Level	100%	
Coolant Level	100%	
Hydraulic fluid level	100%	
Washer fluid level	100%	
Ad-blue level	100%	
Refuelling Hose - present	✓	

Electric		
Cable Connections	✓	
General Cleanliness	✓	
Battery Security	✓	

Other Checks		
Front left wheels		
Front right wheels		
Rear left wheels		
Rear right wheels		

Defects / Service Details / Notes ALL CHECKED OVER. ALL GREASED AND CLEANED AROUND, ALL IN WORKING ORDER

Engineers name: AC	Signature: <i>[Signature]</i>
--------------------	-------------------------------



H296

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	2 x 225-7	Date:	24/04/2026
Fleet Number	H296		
Hour Meter	684 hrs		

Machine Serviced 250  500  1000  Service Computer reset  Service sticker updated

Service due 976 hrs

Plant item	OK	Defect
Rams / bushings	✓	
Cab Guards/Covers	N/A	
Lifting eye / points	✓	
Cab glass	✓	
Chassis bolts & security	✓	
Seat secure & fully adjustable	✓	
Tracks	✓	
Blade / stabilizers if fitted	N/A	
Seat & Seat Belt	✓	
Steering if applicable	N/A	
Brakes as appropriate	N/A	
Bodywork	✓	
Operating Controls	✓	
Warning Lights	✓	
Gauges/Instruments	✓	
Railings / boxing ring	✓	
Fan & other belts / chains	✓	
Fuel cap secured	✓	
Lenses & mirrors	✓	
Rear & 360° cameras	✓	
Horn	✓	
Travel alarm	✓	
Lights / Beacons	✓	
Obvious Leaks	N/A	
Safety pins & bolts	✓	
Floor mats/ Air freshener	✓	

Fuel / Fluids	OK	Defect
Fuel Level	100%	
Fuel connectors & pipes	✓	
Engine Oil Level	100%	
Coolant Level	100%	
Hydraulic fluid level	100%	
Washer fluid level	100%	
Ad-blue level	100%	
Refuelling Hose - present	✓	

Electric	OK	Defect
Cable Connections	✓	
General Cleanliness	✓	
Battery Security	✓	

Other Checks	OK	Defect
Front left wheels		
Front right wheels		
Rear left wheels		
Rear right wheels		

Defects / Service Details / Notes ALL CHECKED OVER. ALL GREASED AND CLEANED OVER.  
ALL IN WORKING ORDER

Engineers name: AC Signature: *[Signature]*