



D122

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE


BIO OIL

Make / Model	THWATER 17	Date:	23/4/26
Fleet Number	D122		
Hour Meter	53 hrs		

Machine Serviced 250 500 1000 Service Computer reset Service sticker updated

Service due	hrs		Fuel / Fluids	OK	Defect
Plant item	OK	Defect			
Rams / bushings	/		Fuel Level	% 100	
Cab Guards/Covers	/		Fuel connectors & pipes	/	
Lifting eye / points	/		Engine Oil Level	/	
Cab glass	/		Coolant Level	/	
Chassis bolts & security	/		Hydraulic fluid level	/	
Seat secure & fully adjustable	/		Washer fluid level	/	
Tracks	/		Ad-blue level	X	
Blade / stabilizers if fitted	/		Refuelling Hose - present	/	
Seat & Seat Belt	/				
Steering if applicable	/		Electric	/	
Brakes as appropriate	/		Cable Connections	/	
Bodywork	/		General Cleanliness	/	
Operating Controls	/		Battery Security	/	
Warning Lights	/				
Gauges/Instruments	/		Other Checks		
Railings / boxing ring	/		Front left wheels	/	100
Fan & other belts / chains	/		Front right wheels	/	100
Fuel cap secured	/		Rear left wheels	/	100
Lenses & mirrors	/		Rear right wheels	/	100
Rear & 360° cameras	/				
Horn	/				
Travel alarm	/				
Lights / Beacons	/				
Obvious Leaks	/				
Safety pins & bolts	/				
Floor mats/ Air freshener	/				

Defects / Service Details / Notes

Engineers name:  Signature: 