



H296

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S

RT

FE

ROTATE

BIO OIL

Make / Model	2 x 225-7	Date:	24/04/2026
Fleet Number	H296		
Hour Meter	684 hrs		

Machine Serviced	250 <input type="checkbox"/>	500 <input type="checkbox"/>	1000 <input type="checkbox"/>	Service Computer reset <input type="checkbox"/>	Service sticker updated <input type="checkbox"/>
------------------	------------------------------	------------------------------	-------------------------------	---	--

Service due	976 hrs
-------------	---------

Plant item	OK	Defect	Fuel / Fluids	OK	Defect
Rams / bushings	✓		Fuel Level	100%	
Cab Guards/Covers	N/A		Fuel connectors & pipes	✓	
Lifting eye / points	✓		Engine Oil Level	100%	
Cab glass	✓		Coolant Level	100%	
Chassis bolts & security	✓		Hydraulic fluid level	100%	
Seat secure & fully adjustable	✓		Washer fluid level	100%	
Tracks	✓		Ad-blue level	100%	
Blade / stabilizers if fitted	N/A		Refuelling Hose - present	✓	
Seat & Seat Belt	✓				
Steering if applicable	N/A				
Brakes as appropriate	N/A				
Bodywork	✓		Electric		
Operating Controls	✓		Cable Connections	✓	
Warning Lights	✓		General Cleanliness	✓	
Gauges/Instruments	✓		Battery Security	✓	
Railings / boxing ring	✓		Other Checks		
Fan & other belts / chains	✓		Front left wheels	/	
Fuel cap secured	✓		Front right wheels		
Lenses & mirrors	✓		Rear left wheels		
Rear & 360° cameras	✓		Rear right wheels		
Horn	✓				
Travel alarm	✓				
Lights / Beacons	✓				
Obvious Leaks	N/A				
Safety pins & bolts	✓				
Floor mats/ Air freshener	✓				

Defects / Service Details / Notes ALL CHECKED OVER. ALL GREASED AND CLEANED OVER.
ALL IN WORKING ORDER

Engineers name:	AC	Signature:	<i>[Signature]</i>
-----------------	----	------------	--------------------